

Printed by EAST

UserID: ARodriguez

Computer: WS11348

Date: 04/19/2001

Time: 16:20

Type	L #	Hits	Search Text	PBS	Time Stamp	Comments	Definition	Err
								CSS
1 IS&R	L11	193	("372/38.02") .CCLS.	USPAT; EPO; JPO; Derwen t	2001/04/19 16:15		0	
2 BRS	L16	8	1. and summing and amplifier	USPAT; EPO; JPO; Derwen t	2001/04/19 16:16		0	
3 IS&R	L11	162	("372/38.07") .CCLS.	USPAT; EPO; JPO; Derwen t	2001/04/19 16:16		0	
4 BRS	L16	11	11 and summing and amplifier	USPAT; EPO; JPO; Derwen t	2001/04/19 16:16		0	
5 IS&R	L21	737	("372/32") .CCIS.	USPAT; EPO; JPO; Derwen t	2001/04/19 16:16		0	
6 BRS	L26	36	21 and summing and amplifier	USPAT; EPO; JPO; Derwen t	2001/04/19 16:17		0	

Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
7 IS&R	L31	671	("372/33").CCIS.	USPAT; EPO; JPO; Derwen	2001/04/19 16:17	t		0
8 BRS	L36	21	31 and summing and amplifier	USPAT; EPO; JPO; Derwen	2001/04/19 16:17	t		0
9 BRS	L41	6724	summing and amplifier and converter and feedback	USPAT; EPO; JPO; Derwen	2001/04/19 16:18	t		0
10 BRS	L46	735	41 and laser	USPAT; EPO; JPO; Derwen	2001/04/19 16:19	t		0
11 BRS	L51	0	46 and 372/4.cc1s.	USPAT; EPO; JPO; Derwen	2001/04/19 16:19	t		0
12 BRS	L56	50	46 and 372/\$.cc1s.	USPAT; EPO; JPO; Derwen	2001/04/19 16:19	t		0